



INDEX NO.	DESCRIPTION	PART NO.	REQ'D NO
1	Jack Base Assembly	N/A	1
2	Ram	621371	1
3	Lever Linkage Assembly	621372	1
4	Pin Link	621373	2
5	Push Nut	621374	2
6	Release Valve	603182	1
*7	O-Ring, M2.4 x 6.3, Kit Only		1
*8	Oil Filler Plug	603192	1
9	Pump Plunger	621378	1
*10	O-Ring, M2.4 x 16, Kit Only		1
*11	Backup Ring, Kit Only		1
12	Snap Ring	621381	1
13	Stuffing Ring	603174	2
*14	O-Ring, M3.6 x 26.2, Kit Only		1
15	Ram Bearing (A)	603177	1
*16	Backup Ring, Kit Only		1
*17	O-Ring M5.3 x 20, Kit Only		1
18	Ram Bearing (B)	621387	1
19	Handle Assembly	612116	1
20	Overload Valve Ball	9004	1
21	Overload Valve Spring	656024	1
22	Overload Valve Plug	656023	1

* Items in Repair Kit 621300

2018

REPLACEMENT PARTS

MODEL NO.
76402B

CAPACITY
1 1/2 TON

DESCRIPTION
LONG HAND BOTTLE JACK

